

事業者名	川重冷熱工業株式会社
------	------------

認定種類	認定番号	認定年月日	代表型式	定格出力 冷房 (kW)	定格出力 暖房 (kW)	その他型式	備考
グレードAA	GAA261005	2026年7月23日	NHJ-0080HQ5A※	281	195	NHJ-0080AN5A※、NHJ-0080AN6A※、NHJ-0080AN7A※、NHJ-0080AN8A※、NHJ-0080AN9A※、NHJ-0080AP5A※、NHJ-0080AP6A※、NHJ-0080AP7A※、NHJ-0080AP8A※、NHJ-0080AP9A※、NHJ-0080AQ5A※、NHJ-0080AQ6A※、NHJ-0080AQ7A※、NHJ-0080AQ8A※、NHJ-0080AQ9A※、NHJ-0080EN5A※、NHJ-0080EN6A※、NHJ-0080EN7A※、NHJ-0080EN8A※、NHJ-0080EN9A※、NHJ-0080EP5A※、NHJ-0080EP6A※、NHJ-0080EP7A※、NHJ-0080EP8A※、NHJ-0080EP9A※、NHJ-0080EQ5A※、NHJ-0080EQ6A※、NHJ-0080EQ7A※、NHJ-0080EQ8A※、NHJ-0080EQ9A※、NHJ-0080HN5A※、NHJ-0080HN6A※、NHJ-0080HN7A※、NHJ-0080HN8A※、NHJ-0080HN9A※、NHJ-0080HP5A※、NHJ-0080HP6A※、NHJ-0080HP7A※、NHJ-0080HP8A※、NHJ-0080HP9A※、NHJ-0080HQ6A※、NHJ-0080HQ7A※、NHJ-0080HQ8A※、NHJ-0080HQ9A※、NHJ-0080MN5A※、NHJ-0080MN6A※、NHJ-0080MN7A※、NHJ-0080MN8A※、NHJ-0080MN9A※、NHJ-0080MP5A※、NHJ-0080MP6A※、NHJ-0080MP7A※、NHJ-0080MP8A※、NHJ-0080MP9A※、NHJ-0080MQ5A※、NHJ-0080MQ6A※、NHJ-0080MQ7A※、NHJ-0080MQ8A※、NHJ-0080MQ9A※、NHJ-0080SN5A※、NHJ-0080SN6A※、NHJ-0080SN7A※、NHJ-0080SN8A※、NHJ-0080SN9A※、NHJ-0080SP5A※、NHJ-0080SP6A※、NHJ-0080SP7A※、NHJ-0080SP8A※、NHJ-0080SP9A※、NHJ-0080SQ5A※、NHJ-0080SQ6A※、NHJ-0080SQ7A※、NHJ-0080SQ8A※、NHJ-0080SQ9A※、NHJ-0080WN5A※、NHJ-0080WN6A※、NHJ-0080WN7A※、NHJ-0080WN8A※、NHJ-0080WN9A※、NHJ-0080WP5A※、NHJ-0080WP6A※、NHJ-0080WP7A※、NHJ-0080WP8A※、NHJ-0080WP9A※、NHJ-0080WQ5A※、NHJ-0080WQ6A※、NHJ-0080WQ7A※、NHJ-0080WQ8A※、NHJ-0080WQ9A※、NHG-0080AN5A※、NHG-0080AN6A※、NHG-0080AN7A※、NHG-0080AN8A※、NHG-0080AN9A※、NHG-0080AP5A※、NHG-0080AP6A※、NHG-0080AP7A※、NHG-0080AP8A※、NHG-0080AP9A※、NHG-0080AQ5A※、NHG-0080AQ6A※、NHG-0080AQ7A※、NHG-0080AQ8A※、NHG-0080AQ9A※、NHG-0080EN5A※、NHG-0080EN6A※、NHG-0080EN7A※、NHG-0080EN8A※、NHG-0080EN9A※、NHG-0080EP5A※、NHG-0080EP6A※、NHG-0080EP7A※、NHG-0080EP8A※、NHG-0080EP9A※、NHG-0080EQ5A※、NHG-0080EQ6A※、NHG-0080EQ7A※、NHG-0080EQ8A※、NHG-0080EQ9A※、NHG-0080HN5A※、NHG-0080HN6A※、NHG-0080HN7A※、NHG-0080HN8A※、NHG-0080HN9A※、NHG-0080HP5A※、NHG-0080HP6A※、NHG-0080HP7A※、NHG-0080HP8A※、NHG-0080HP9A※、NHG-0080HQ5A※、NHG-0080HQ6A※、NHG-0080HQ7A※、NHG-0080HQ8A※、NHG-0080HQ9A※、NHG-0080MN5A※、NHG-0080MN6A※、NHG-0080MN7A※、NHG-0080MN8A※、NHG-0080MN9A※、NHG-0080MP5A※、NHG-0080MP6A※、NHG-0080MP7A※、NHG-0080MP8A※、NHG-0080MP9A※、NHG-0080MQ5A※、NHG-0080MQ6A※、NHG-0080MQ7A※、NHG-0080MQ8A※、NHG-0080MQ9A※、NHG-0080SN5A※、NHG-0080SN6A※、NHG-0080SN7A※、NHG-0080SN8A※、NHG-0080SN9A※、NHG-0080SP5A※、NHG-0080SP6A※、NHG-0080SP7A※、NHG-0080SP8A※、NHG-0080SP9A※、NHG-0080SQ5A※、NHG-0080SQ6A※、NHG-0080SQ7A※、NHG-0080SQ8A※、NHG-0080SQ9A※、NHG-0080WN5A※、NHG-0080WN6A※、NHG-0080WN7A※、NHG-0080WN8A※、NHG-0080WN9A※、NHG-0080WP5A※、NHG-0080WP6A※、NHG-0080WP7A※、NHG-0080WP8A※、NHG-0080WP9A※、NHG-0080WQ5A※、NHG-0080WQ6A※、NHG-0080WQ7A※、NHG-0080WQ8A※、NHG-0080WQ9A※	※製修番号が9N23574以降かつバーナー型式が「LGXLU 30-1HA」のものに限る。
グレードAA	GAA203001	2021年2月2日	NHJ-0080HN5A※	281	199	NHJ-0080AN5A※、NHJ-0080AP5A※、NHJ-0080AQ5A※、NHJ-0080AN7A※、NHJ-0080AP7A※、NHJ-0080AQ7A※、NHJ-0080AN9A※、NHJ-0080AP9A※、NHJ-0080AQ9A※、NHJ-0080EN5A※、NHJ-0080EP5A※、NHJ-0080EQ5A※、NHJ-0080EN7A※、NHJ-0080EP7A※、NHJ-0080EQ7A※、NHJ-0080EN9A※、NHJ-0080EP9A※、NHJ-0080EQ9A※、NHJ-0080HP5A※、NHJ-0080HQ5A※、NHJ-0080HN7A※、NHJ-0080HP7A※、NHJ-0080HQ7A※、NHJ-0080HN9A※、NHJ-0080HP9A※、NHJ-0080HQ9A※、NHJ-0080MN5A※、NHJ-0080MP5A※、NHJ-0080MQ5A※、NHJ-0080MN7A※、NHJ-0080MP7A※、NHJ-0080MQ7A※、NHJ-0080MN9A※、NHJ-0080MP9A※、NHJ-0080MQ9A※、NHJ-0080SN5A※、NHJ-0080SP5A※、NHJ-0080SQ5A※、NHJ-0080SN7A※、NHJ-0080SP7A※、NHJ-0080SQ7A※、NHJ-0080SN9A※、NHJ-0080SP9A※、NHJ-0080SQ9A※、NHJ-0080WN5A※、NHJ-0080WP5A※、NHJ-0080WQ5A※、NHJ-0080WN7A※、NHJ-0080WP7A※、NHJ-0080WQ7A※、NHJ-0080WN9A※、NHJ-0080WP9A※、NHJ-0080WQ9A※、NHG-0080AN5A※、NHG-0080AP5A※、NHG-0080AQ5A※、NHG-0080AN7A※、NHG-0080AP7A※、NHG-0080AQ7A※、NHG-0080AN9A※、NHG-0080AP9A※、NHG-0080AQ9A※、NHG-0080EN5A※、NHG-0080EP5A※、NHG-0080EQ5A※、NHG-0080EN7A※、NHG-0080EP7A※、NHG-0080EQ7A※、NHG-0080EN9A※、NHG-0080EP9A※、NHG-0080EQ9A※、NHG-0080HN5A※、NHG-0080HP5A※、NHG-0080HN7A※、NHG-0080HP7A※、NHG-0080HN9A※、NHG-0080HP9A※、NHG-0080HQ5A※、NHG-0080HQ7A※、NHG-0080HQ9A※、NHG-0080MN5A※、NHG-0080MP5A※、NHG-0080MQ5A※、NHG-0080MN7A※、NHG-0080MP7A※、NHG-0080MQ7A※、NHG-0080MN9A※、NHG-0080MP9A※、NHG-0080MQ9A※、NHG-0080SN5A※、NHG-0080SP5A※、NHG-0080SQ5A※、NHG-0080SN7A※、NHG-0080SP7A※、NHG-0080SQ7A※、NHG-0080SN9A※、NHG-0080SP9A※、NHG-0080SQ9A※、NHG-0080WN5A※、NHG-0080WP5A※、NHG-0080WQ5A※、NHG-0080WN7A※、NHG-0080WP7A※、NHG-0080WQ7A※、NHG-0080WN9A※、NHG-0080WP9A※、NHG-0080WQ9A※	※製修番号が9N22329から9N23573までかつバーナー型式が「LGXLU 30-1H」のものに限る。